

# 板件维修

ATE / Prober Board Repair Service

- ✓ 交期短：本地维修，板卡无需经历报关过程，降低整体维修周期
- ✓ 成本低：本地维修，不需报关费用，可大幅降低维修及寄送成本
- ✓ 经验足：团队成员均有十年以上原厂经验，涉及机型范围广泛

## ● 服务优势

客户面临的板件维修问题

封测设备  
原厂保固失效

境外维修  
时间费用成本高



蔚华科技 - 板件维修服务

✓ 扩大服务能量，提供各类板卡  
**及时、高性价比、本地化**的维修服务

## ● 业务范围 (详细列表请参照背面信息)

**Advantest** V93K-PS1600 / PS800 / PS400 / C400 / C400e / P600  
ND3 / ND4

**Teradyne** M2 / M5  
J750/UFLEX

**Cohu** ASL1K / ASL3K / ASLX  
D10 / Diamondx  
KALOS / KALOS2

**Yokogawa** ST6730 / TS6700

**Others** PAX / AMIDA / Other Equipment PCB & Power Supplies



Cohu D10



ACCRETECH UF3000

## ● 板件维修服务详细清单

ADVANTEST	
机种	板件名称
HP93000	001-DC/DC Board(Digital)
	002-DC/DC Board(Analog)
	003-Channel Board(P)
	004-PDS(GP)
	005-PDS(MS)
	006-Clock Board
	007-Channel Board(Ce)
	008-AC/DC Board
	009-Support AC/DC Board
	010-Channel Board(C)
	011-Control Board
	012-CIC Card
	013-GPIB Box
	014-Power Control Board
	015-BackPlane Board
	016-FrontPlane Board
PS1600	001-Channel Board
	002-Channel Board(9G)
	003-DPS 32 Board(CS)
	004-DC/DC Board
	005-AC/DC Board
	006-MCA Board
	007-MCB Board
	008-Power Control Board
	009-BackPlane Board
	010-FrontPlane Board
011-Clock Board	
PS400	001-Channel Board
	002-Channel Board(3600)
	003-DC/DC Board
	004-AC/DC Board
	005-MCA Board
	006-MCB Board
	007-Power Control Board
	008-BackPlane Board
	009-FrontPlane Board
	010-Clock Board
ND4	001-LCDPE
	002-RVS32
	003-GVI64
	004-AQM
	005-DM1R6GBPS
	006-CUTI
	007-RC5V192E
	008-SGM208
	009-BUS SW
	010-MT CONT
	011-RND300 HIFIX
	012-MAIN AC
	013-Cooling Unit
	014-TSC4L
	015-Diag Board
	016-Cal Board
	017-CALPB-S
	018-Diag Board-Type3,4
	019-GBI Board
	020-UHSIF
	021-Type 5 Hifix
ND3	001-LCDPE
	004-PE Card
	002-HVDC
	003-UPS
	005-TC Unit
	006-HSIF Board
	007-STICK Board
	008-RVS Board
	009-HSIF HIFIX
	010-HSIF Diag Board
	011-NDPPS Board
	012-Normal HIFIX Board
	013-Transformer
	014-SQPG
	015-TC Unit(7B)
	016-Normal Diag Board

CREDENCE	
机种	板件名称
ASL1K/3K/X	001-DVI200
	002-DVI300
	003-DVI2000
	004-OVI20
	005-OVI30
	006-HVS600
	007-HVS850
	008-DOAL
	009-ACS
	010-PV3
	011-LCB/LCB2
	012-SCB/SCB2
	013-POWER SUPPLY
	014-POWERSEQUENCING
	015-BACKPLANE
	016-CALDUT
	017-XVI
	018-MUX_LV
	019-MUX_HV
	020-WORKSTATION
	021-TMU
	022-DCC
	023-DDD128
	024-DDD8
025-INTERFACE CARD	
D10	001-DPIN96-16M/32M/64M
	002-DPS16
	003-VIS16
	004-MULTIWAVE
	005-DIBU
	006-HDVI
	007-POWER SUPPLY
	008-WORKSTATION
	009-BACKPLANE
	010-AWG Board
	011-DIG Board
DX	001-DPIN96-16M/32M/64M
	002-DPS16
	003-VIS16
	004-MULTIWAVE
	005-SDU
	006-HDVI
	007-POWER SUPPLY
	008-WORKSTATION
	009-BACKPLANE
	010-GX1
	011-PD2
012-PSM1	
013-PMVI	
014-MP1	
015-AC-DC Converter 48V PS	
016-CALDIAG Finger Board	
017-BACKPLANE	
KALOS	001-K1MB
	002-K2MB
	003-POWER SUPPLY

TERADYNE	
机种	板件名称
M2	001-Site Assembly Board(HSBs)
	002-Intelligent Power Controller Board(IPC)
J750	001-PIB Board
	002-Power Supply PPT-1830
	003-HDVIS Board
	004-CUB Board
	005-HSD800
	006-TDDI PIB
	007-HDDPS
	008-Power 405-920
	009-Power 405-924
	010-Power 405-325
011-Power 405-925	
012-Power 535-100-02	

OTHERS	
机种	板件名称
PAX	001-OVI
	002-HCOVI
	003-3U DC POWER SUPPLY
	004-WORKSTATION
	005-SSBA
AMIDA	001-HVI
	002-POWER SUPPLY

如欲维修板件未在表格中，欢迎送到蔚华维修中心进行诊断。  
深信以蔚华团队的维修技术，一定可以协助您解决板件问题！

Contact us

上海市浦东新区祖冲之路1077号2幢3201室  
+86 (21) 6108 1858 #3121  
marketing@spirox.com

